

Community Meeting 6/11/03 4:00 PM at Pioneer HS					
SCHOOL	NAME	PHONE #	Representing	NOTES	ACTION TAKEN
Castillero Middle					
	Sandy Engel	408-535-6385		1. Why S5.3 no money amount?	Included in Measure 'C' currently underway
		408-268-1973		2. No science lab upgrade is being done at this site	
				3. Request drawings for locker room	
				4. Trip hazards for hardscape areas should be addressed prior to 2006	
				5. Need to know scope of work for 2.6	Undefined at this time - will be reviewed by future design/consultation process
				6. Student lockers should be a higher priority	
				7. Why isn't S4.6 - \$1 million	adjustment has now been made
				8. Need list of specialized instructional programs	Included within Imp. Plan document
				9. How come we do not have cost to replace stage curtain?	
				10. Concerned about location of S2.8, investigate moving to near back service road	
				11. Suggest combining Measure C parking lot work with Measure F parking lot work	
				12. Concern for locker room plan	
				13. No stairs required for raised office in locker room (no raised office)	
				14. S3.6 no lift for locker room office (office is ground level)	
				15. Site locations should have administration input prior to starting design	
				16. Why aren't counters and sinks included in the budget?	
Erikson Elementary School					
	Milly Powell	408-224-9456	Erikson (Principal)	1. S3.1 stage curtain is needed. But no cost is included.	
				2. S3.5 - restrooms are done in the admin bldg a few years ago, with the exception of the Nurse's room.	
				3. Bus drop off is a huge concern. There's been talk about adding a curb with chain/poles to separate cars and buses. Russ Taff of the City and Steve Mitchell of SJUSD are involved.	
				4. Some portables need carpet replacement (rooms 18,19,20,21,22)	
				5. Add trash enclosure is #2 priority	
				6. Kindergarten area once had a playground equipment but it was taken out. Want to put the playground equipment back in	
				7. Sinks and counters in portables, see plans for detail. Some portables already have sinks, where as some do not.	
Almaden Elementary School					
	Miguel Montes	408-535-6207	Almaden (Principal)	1. Drainage overflow from gutter. A design problem. Needs to be corrected.	review during future design/consultation process
				2. Cafeteria needs with kitchen ventilation problem!	review during future design/consultation process
				3. Close open space in Main Building	Currently not planned to enclose classrooms with walls
				4. Move restroom renovation from 2006 to 2004	
Reed Elementary School					
	Shyrl McGuiness	408-535-6247	Reed E.S.	1. Need right away paved dirt area for additional parking - right now it is a dirt area (dirt area is right next to parking lot) should be done 1st! Overflow dirt area for parking needs to be paved.	

Community Meeting 6/11/03 4:00 PM at Pioneer HS					
SCHOOL	NAME	PHONE #	Representing	NOTES	ACTION TAKEN
Steinbeck Middle School					
	Greg West	408-629-1930	CBOC		
John Muir Middle School					
	Shannon McGee	408-535-6281	Muir	1. Track - placement of a full size track on the school campus *Discussed during last "modernization" but did not occur!!	
Carson Elementary School					
	Bob Enz	408-535-6287	Carson (Principal)	1. S1.1 playground in fine shape. Change improvements to larger tan bark play area adjacent to room 22 2. Add restroom where? 3. Add concrete flatwork adjacent to portables and playground 4. S2.1 underground utility lines - where? What lines? 5. What is improvement for S2.6? Listed 3 times - priority #1, #3, #4 with same dollar amount 6. S3.12 kitchen modernized summer 02, why \$160,893	review during future design/consultation process Budget is currently an allowance for needed repair/replacement Work scope is undefined at this time
Terrell Elementary School					
	Anita Sunseri	408-535-6255	Terrell Elementary	1. Parking lot at end of Terrell court labeled S2.6 athletic fields? Is that in error? 2. Exterior lighting at end of Terrell court parking lot - no notice its included 3. Wall of classroom building has holes in stucco, bees residing there 4. Gutters at boys and girls bathroom are leaking on both of the long sides. S5.2 doesn't show inclusion of this repair. 5. The site plan shows keynote S2.8 and illustrates a bus drop-off. But the estimate shows zero dollar for this work 6. Make sure adequate soundproofing between new admin and multi. *Keep cafeteria use as cafeteria - use new multi function as auditorium 7. Would like to keep current multi - as a meeting facility/auditorium, so it didn't have to double as food service	Maintenance issue Maintenance issue
Hammer Elementary School					
	Barbara Stephens	408-535-6470	Hammer (Teacher)	1. Hot Buttons - We would like quickly : (1) 4 new sinks for our portable classrooms. Need very badly right away (and water fountains.) (2) Replacement windows for our original buildings that just have metal slats. (3) We need a kinder playground for young kids 3-5 yrs. old	(a) Sinks and water fountain installed via Scope D (b)
	Diane Hemmes	408-535-6470	Hammer (Principal)	2. Current restrooms do not need to be renovated	
	Renee Hazarian	408-978-5582	Parent	3. Windows in classrooms with metal slats are nailed shut. Need to be replaced with windows.	
	Lynn Belmonte	408-535-6470	Teacher	4. Barbara Stephens: Where is the funding for the kinder playground? We had a plan for the playground worked out with the District in March of 2002	
	Bryan Ruttenberg	408-269-8969	Parent	5. Hammer has whiteboards - please check what is needed	delete from estimate/budget
	Camille Manley	408-448-1673	parent	6. Hammer has four classrooms without sinks 7. Hammer did not benefit from Measure C, we did not receive air conditioning or any upgrades / modernization 8. Hammer needs windows on original buildings. Original building have slat windows that are metal 9. Hammer does not need a stage curtain	delete from estimate/budget

Community Meeting 6/11/03 4:00 PM at Pioneer HS					
SCHOOL	NAME	PHONE #	Representing	NOTES	ACTION TAKEN
				10. E-mail from Renee Godette: Classroom Sinks. Four (4) of our classrooms do not have sinks. In the Implementation Plan it lists sinks as a level three priority. As a parent and health care professional, I believe that having a sink in every elementary classroom should be a top level priority for our district. The CDC, Center for Disease Control, has research data that proves hand washing is the most important thing that one can do to keep from getting sick. Remembering that, in addition to colds, some very serious diseases like Hepatitis A, Meningitis and Infectious Diarrhea, can easily be prevented with hand washing! This is a simple and inexpensive measure to serve against disease.	
				11. Kindergarten Playground. Our Kindergarten Playground was removed last year and has not been replaced. To the best of my knowledge all other SJUSD elementary sites have a separate, safe, age-appropriate playground for the kindergarten children. Play structure expansion at Hammer in 2001 was provided by a \$40k SJ City grant secured by myself. The grant was to complete the play structure for which Sjust did not have funds available when the school originally re-opened in 1997. At that time our children were only able to access the play structure 1 day per week due to its small size. There is no playground budget line in Measure F implementation plan.	
				12. Window replacement. None of the original classrooms at Hammer Montessori have been upgraded with air conditioning. Only portable classrooms at our site have air conditioning and half of the classrooms have the original 1950 circa louvered windows of which many are nailed shut. This poses not only comfort concerns but safety concerns as well.	
				13. Measure F Project Schedule. Our PTA purchased a new Stage Curtain in March 2002 and each of our classrooms has at least one whiteboard which are upcoming improvements scheduled for our school. Not until late Q2 2009 if at all will the construction priorities listed above begin to be addressed. The Hammer Montessori school community asks that our construction priorities be addressed in the 2002-03 school year.	
Hacienda Elementary School					
	Susan Olsen	408-535-6259	Hacienda	1. Hacienda Recommendations: (1) Safety drop-off zone for parents in lot on Kimberly (now vacant) (2) Monitor moving equipment use - Re: prevent heavy equipment making ruts on rainy days. (3) Reconfiguration admin office *many rooms too small for their use. Relocate science? Openings may be required in structural walls *Talk to Joe	
	Jennifer Nance	408-535-6259	Hacienda	2. Athletic fields and sportcourts: listed as priorities 1,2,3, and 4 all with some \$ and descriptions??	review during future design/consultation process
	Sharon Clark		Hacienda Parent		
	Farrell Podgorsek		Hacienda		
	Dorothy Kennedy	408-535-6627	Hacienda		
Pioneer High School					
	Kaia Hamilton		Pioneer	1. Sequence of field renovation will greatly effect student choice of schools. Example - school A done in Fall 03, school B slated for Fall 06. Students may choose based on sequence. How is this issue going to be addressed?	
		408-535-6310			

Community Meeting 6/11/03 4:00 PM at Pioneer HS					
SCHOOL	NAME	PHONE #	Representing	NOTES	ACTION TAKEN
	Blaine Hashimoto	408-535-6310	Pioneer	2. (1) Expand and/or reline parking lot to increase spaces for student parking and activities on campus. Would better relationship with neighbors. (2) Alarm system for performing arts center has break-in problem this year. (3) Create bus drop off is a safety issue. It will reduce traffic problem on Blossom Hill. (4) Lights for parking lots is a student safety issue	
	Jake Hernandez	408-535-6310	Pioneer	3. Rob Zaccheo (Science Dept) S.3.1 shows in incorrect classrooms. Priority#1 - Room 309; Priority #2 - Room 201 (to chemistry); Priority #3 - Room 300 + 101; Priority#4 - Room 301; Furniture in all rooms needs upgrade?	
	Mark Krail	408-535-6310	Pioneer (athletic director)	4. Rob Zaccheo: Science instruction will take a big hit if science teachers need to leave their classroom to have work done in their room in mid year.	
	Barbara Lepiane	408-535-6310	Pioneer (Principal)	5. Rob Zaccheo: S3.1 - Science rooms need much more work than new tables / cabinetry, lab setup station, electricity, etc.	
	Joan Cooper	408-723-0251	Pioneer PTA	6. Rob Zaccheo: S3.1 - there is no room 200B at Pioneer?	
	Ja Nelim	408-268-7180	athletic	7. Rob Zaccheo: Room 309 needs to be upgraded to a science facility. Room 201 needs to be upgraded to a chemistry classroom	
	Maureen Noel	408-266-7183	Pioneer PTA	8. Relocate athletic fields; synthetic dedicated athletic fields; lights; soundwalls (fencing) to enclose athletic complex	
	Marge Kregel	408-535-6310	Pioneer	9. The request for synthetic baseball and softball fields. This would save money on sprinkler and irrigation issues. Less maintenance is always a positive	
	Robert K. Zaccheo	408-535-6310	Pioneer	10. With fewer buses, we will need more student, parent and visitor parking. Increased number of students means more teacher parking too. There is no on-street parking at Pioneer (safety issue).	
	John Cimino	408-535-6071	Construction	11. Lighting in back parking lot and on campus	refer to Alfa Tech Report and future design/consultation process
				12. (1) The athletic program is very interested in a lighted track - football - soccer facility. We would like an opportunity to make this happen. (2) We also would like dedicated fields for football - baseball - softball - soccer. (3) We would like to see a synthetic practice / game field in addition to the football/soccer complex.	
				13. Secure: (1) fencing along athletic fields and parking areas is a must. Huge safety issue. Community/parent issue. (2) External Lighting - Safety Issue throughout campus that back hoffman court. Constant vandalism. Huge parent concern. (3) Expand the parking area, school population has grown. Parking is a danger issue. Move fence + Pave into field area	
				14. Science facilities need a major uphall and I'm not sure \$286,000 is enough	
Canoas Elementary School					
	Carol Garcia	408-535-6391	Canoas	1. Most important is modernization of west wing and kindergarten rooms. Code, safety issues - super dry rot!	
				2. S1.2, 3.2, 3.3, 3.4, 3.10 (roofing), S3.11 need to be priority 1, not 2 and 3. Need S3.14 in west wing and kinder room	
				3. S3.1 on priority chart does not indicate roofing. Need roofing.	
				4. Don't need portable replacement.	delete from estimate/budget
				5. Need to control flooding in area S2.7 and west play area	

Community Meeting 6/11/03 4:00 PM at Pioneer HS					
SCHOOL	NAME	PHONE #	Representing	NOTES	ACTION TAKEN
				6. Fencing around east parking lots needed to prevent cars from cutting through property from Wren Drive to Patkin Lange.	
				7. S4.1 Portables need to be for classrooms, not preschool leave preschool portable already located by east parking lot.	
Randol Elementary School					
	Cheryl Connolly	408-997-2166	Randol	1. Peepholes need to be complete prior to 2008 - hopefully 2004	
	Cheryl Cognetti	408-227-6572	Randol	2. Any sound proofing in the large building between the four rooms in back of the four pods	
	Marcol Slaughter	408-998-0977	Randol	3. Staff bathrooms needed - upgrade. In student bathrooms, give health office top priority	
	Linda Kaher		Randol	4. Casements rusted in various places including room 6.	review during future design/consultation process
	Cheryl Washington	408-535-6251	Randol	5. Lock down safety bars which can be locked from the inside	review during future design/consultation process
				6. Safety - replacement refrig and bedding in health office	Maintenance issue
				7. Curtains in media center, cafeteria, and P-Z1	
				8. Move glazing from 2008 to 2004	
				9. Front of school, S2.2 do not need benches. Benches surrounding permanent building (perimeter) in need of repair. Improper drainage at P21, 22, 23 - water "floods" the classrooms. Sandbags needed yearly.	
Gunderson High School					
	Bob Ferber	408-268-6739		1. Micro? Gunderson priority 2 - S3.14 building PA will system function during power outage, earthquake, etc?	
				2: Bob: (1) UPS Back up to Micro-turbine (2) Lighting at E9 and E10	